


PLAN VIEW

GENERAL NOTES:

- 1. COORDINATE WITH COA STAFF.
- 2. INSCRIBE "W", "S", OR "V", AS APPLICABLE.
- 3. SPRAY, PAINT 307 OVER AND AROUND INSCRIPTION. COLOR AS SHOWN.



CURB MARKINGS FOR WATER METERS, SANITARY CLEANOUTS, AND WATER VALVES NTS

