

## **GENERAL NOTES:**

- A. REMOVE EXISTING PLUGS FROM EXISTING STUB-OUTS.
- B. IT IS ASSUMED THAT EXISTING LATERAL STUB-OUTS ARE INSTALLED AT 45° ABOVE HORIZONTAL. IF NOT, CONTACT THE ENGINEER OR CITY.
- C. CLEAN EXISTING STUB-OUT AND NEW PIPE PRIOR TO INSTALLING COUPLING.

## **KEYED NOTES:**

- $\overline{1}$  INCLUDES CLAMP AND SHEAR RING.
- CONNECT PIPE TO BOTTOM OF CLEAN-OUT. DO NOT CONNECT PIPE TO RISER SECTION OF CLEAN-OUT.



INSTALLING SERVICE LATERALS TO EXISTING CLAY STUB-OUTS

NTS

