



GENERAL NOTES:

1. TRACKER WIRE NOT REQUIRED FOR GRAVITY WW PIPE.
2. AT EACH CLEANOUT, PROVIDE A BURIED ELECTRONIC MARKER.

ADDITIONAL GENERAL NOTES: SEE (321A)

(321D)

**WASTEWATER GRAVITY SYSTEM
BURIED ELECTRONIC MARKER.**

NTS

